Number of LUNs supported on Raid Manager

RM6.11

| | | 02.05.01 | 2.6 | S7 |
|------|---------------|----------|---------------------------|-----------------------|
| SCSI | Sbus (UDWIS) | 8 | 16 LUNs with 2.6 5/98 | 16 |
| | PCI (X6541A)) | 8 | 8 LUNs | 8 LUNs |
| | | | 16 LUNs to be tested with | 16 LUNs pending GLM |
| | | | patch 105580 by SQE | patch release and SQE |
| | | | | testing |

RM6.22

| | | 02.05.01 | 2.6 | S 7 |
|------|-------------------|---------------|---------------------------|-----------------------|
| SCSI | SBus (UDWIS) | Not supported | 32 LUNs with 2.6 5/98 | 32 |
| | PCI (X6541A) | Not supported | 32 LUNs to be tested with | 8 LUNs |
| | | | patch 105580 | 32 LUNs pending GLM |
| | | | | patch release and SQE |
| | | | | testing |
| FC | Sbus (SOC+) | Not supported | 32 LUNs with patch | 32 LUNs with patch |
| | | | 105375-13 or later | 107469-01 or later |
| | PCI (Qlogic 2100) | Not supported | 16 LUNs with patch | 16 LUNs with patch |
| | | | 107280-02 or later | 107292-02 or later |